



Laser Mirror and Lens optimum Setup

Insure Frames,Rails and mirrors are Parallel and Square in both Vertical and Horizontal



Adjust the four corners of the work Table to be the same distance below the frame
 The cut should be 90 degree through Sample edge in both X and Yaxis
 Use the following Samples to Test Engrave,mark,and Cut in 6mm MDF then visual inspection to check



Engrave 50% 250mm/Sec
 Marking P15 20mm/Sec
 Cutting P75 4mm/Sec
 50 Watt _____

